

Inspection Report

Permit Holder: VERMILION ENERGY INC.

Inspection: 2026-3090

Inspection Date: 2026-08-25

Inspection Outcome: Inspected

Inspection Comment:

Site 01-33-081-14 was inspected at or about 1040 hours, it was 16 & sunny.

It was 20, sunny, with wind at 4 km (98E), gust to 11 km. The pond is full, sludge accumulation in N/ NE side of pond. Industrial odor at east end - no active on site at this time.

Complaint direct to officer, regarding the night of August 23rd and days prior.

Discussion with Vermilion confirm treatments planned to start August 26th.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100115429

Facility ID: 00027561

Facility Name: VERMILION MICA 01-33-081-14 001

Facility Type: Water Hub

Location: DLS: 01-33-081-14

Permit Holder: VERMILION ENERGY INC.

Authorized by BCER