

Inspection Report

Permit Holder: Cardinal Energy Ltd.
Inspection: 2026-3091
Inspection Date: 2026-08-25
Inspection Outcome: Inspected

Inspection Comment:

Site 08-34-081-14 was inspected at or about 1020 hours, it was 20 & sunny. The following was included in the inspection:
Access and signage: Signage clear and legible, low grade, rutted access
Site: Wellsite clean, dry rutted and no vegetation concerns, barricades in place
Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns
Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006236
Well ID: 04399
Well Name: CARDINAL MICA 08-34-081-14
Location: DLS: 08-34-081-14

Permit: 100006236
Facility ID: 00018756
Facility Name: CARDINAL MICA 08-34-081-14 001
Facility Type: Well Facility
Location: DLS: 08-34-081-14

Permit Holder: Cardinal Energy Ltd.

Authorized by BCER