

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3108
Inspection Date: 2026-08-25
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris but is overgrown around meter building and riser site. ESD(s) and scv(s) at wellhead good. DW chem tank(s) and pigging station(s) are good.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100064626
Well ID: 24150
Well Name: OVV ECOG HZ SWAN B- 094-A/093-P-09
Location: NTS: B- 094-A/093-P-09

Permit: 100064627
Well ID: 24151
Well Name: OVV ECOG HZ SWAN B-A094-A/093-P-09
Location: NTS: B-A094-A/093-P-09

Permit: 100064628
Well ID: 24152
Well Name: OVV ECOG HZ SWAN B-B094-A/093-P-09
Location: NTS: B-B094-A/093-P-09

Permit: 100064629
Well ID: 24153
Well Name: OVV ECOG HZ SWAN B-C094-A/093-P-09
Location: NTS: B-C094-A/093-P-09

Permit: 100064630
Well ID: 24154
Well Name: OVV ECOG HZ SWAN B-D094-A/093-P-09
Location: NTS: B-D094-A/093-P-09

Permit: 100064626
Facility ID: 00023516
Facility Name: OVV HERITAGE B-094-A/093-P-09 001
Facility Type: Well Facility
Location: NTS: B- 094-A/093-P-09

Permit: 100064627
Facility ID: 00023517
Facility Name: OVV HERITAGE B-094-A/093-P-09 002
Facility Type: Well Facility
Location: NTS: B- 094-A/093-P-09

Permit: 100064628
Facility ID: 00023518
Facility Name: OVV HERITAGE B-094-A/093-P-09 003
Facility Type: Well Facility
Location: NTS: B- 094-A/093-P-09

Permit: 100064629
Facility ID: 00023519
Facility Name: OVV HERITAGE B-094-A/093-P-09 004
Facility Type: Well Facility
Location: NTS: B- 094-A/093-P-09

Permit: 100064630
Facility ID: 00023520
Facility Name: OVV HERITAGE B-094-A/093-P-09 005
Facility Type: Well Facility
Location: NTS: B- 094-A/093-P-09

Authorized by BCER