

Inspection Report

Permit Holder: Ish Energy Ltd.
Inspection: 2026-3119
Inspection Date: 2026-08-25
Inspection Outcome: Inspected

Inspection Comment:

WA# 19997 - Aug. 25, 2026, 10:29 hrs. on site.

Wellhead: SCVA ball valve was found in the open position, no LEL gas was measured (Altair-5x), and no flow was observed. Injection well = "Active Status".

Signage posted is compliant to standards.

Well Facility: Cata-dyne regulator vent line present.

Flowlines: flowlines are connected to wellhead.

Sow Thistle was noted on site.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100050102
Well ID: 19997
Well Name: ISH DESAN A- 008-D/094-P-07
Location: NTS: A- 008-D/094-P-07

Permit: 100049937
Pipeline Project ID: 000015813
Segment IDs (Location): 2 (From NTS: A- 008-D/094-P-07 To NTS: A- 018-D/094-P-07)

Authorized by BCER