

Inspection Report

Permit Holder: Ish Energy Ltd.
Inspection: 2026-3122
Inspection Date: 2026-08-25
Inspection Outcome: Inspected

Inspection Comment:

WA# 6236 - Aug. 25, 2026, 10:46 hrs. on site. Joint field inspection with ISH field staff.

Wellhead: Injection Well: no SCV pipe attached - exemption in place.

Signage is compliant to standards.

Well Facilities: Cata-Dyne regulator vent lines present. Service records inspected on site: meter calibration date: 2024 and orifice plate service date: 2024.

Storage: 1) single wall metal tank (1x) in plastic, grounded, and SDS labels present, 2) double wall tanker (1x), grounded and SDS labels present, and 3) double wall tanker (1x), grounded and SDS labels present. Open pail and catchment tray disposed of by ISH staff.

Flowline: flowline is connected to wellhead and pipeline. Pig barrel chain is installed/attached to the PAV by ISH staff at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100009116
Well ID: 06236
Well Name: ISH ET AL DESAN D- 085-L/094-P-02
Location: NTS: D- 085-L/094-P-02

Permit: 100061960
Facility ID: 00001954
Facility Name: ISH DESAN D-085-L/094-P-02 001
Facility Type: Satellite Battery
Location: NTS: D- 085-L/094-P-02

Permit: 100009190
Pipeline Project ID: 000004056
Segment IDs (Location): 3 (From NTS: D- 085-L/094-P-02 To NTS: D- 095-L/094-P-02)



Inspection Number: 2026-3122
Inspection Date: 2026-08-25

Letter ID: L2604423
Letter Date: 2026-08-26

Authorized by BCER