

Inspection Report

Permit Holder: Ish Energy Ltd.
Inspection: 2026-3123
Inspection Date: 2026-08-25
Inspection Outcome: Inspected

Inspection Comment:

WA# 9520 and 12532 (A) - Aug. 25, 2026: 10:57 hrs. on site.

Wellhead (WA#12532 (A)): SCVA ball valve is in the open position, no LEL gas was measured, and no flow was observed.

Kermit reported gas production rate: 2026-07 (Active Status).

Signage is not compliant to standards.

Well Facilities: N/A - none established on site (processing as satellite facility).

Storage: 1) double wall metal tank (2x), grounded, and SDS labels present. 2) double wall (2x) on metal skid, grounded, and SDS labels present.

Flowline: flowline connected to wellhead and pipeline (control valves closed at time of inspection). ESD PSHL monitors are padlocked / valves open = compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100018093
Well ID: 09520
Well Name: ISH ET AL DESAN B- 084-L/094-P-02
Location: NTS: B- 084-L/094-P-02

Permit: 100025538
Well ID: 12532
Well Name: ISH HZ DESAN B-A084-L/094-P-02
Location: NTS: B-A084-L/094-P-02

Authorized by BCER



Inspection Number: 2026-3123
Inspection Date: 2026-08-25

Letter ID: L2604424
Letter Date: 2026-08-26