

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3135

Inspection Date: 2026-08-25

Inspection Outcome: Inspected

Inspection Comment:

Site 14-20-081-13 was inspected at or about 1110 hours, it was 21 & sunny. The following was included in the inspection:

Access and signage: Signage clear and legible, bridge 4 delineators, rails and running surface free of obvious damage, fresh gravel on approach. From second gate (closest to site) access is rutted

Site: Wellsite clean, dry with ruts and no vegetation concerns

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no barricades at/ near wellhead (2 gates into site both open)

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Chemical tanks: leaks, grounds, caps, - no concerns

Riser & pig stations: chains, grounds, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100071252

Well ID: 26371

Well Name: CNRL MICA 14-20-081-13

Location: DLS: 14-20-081-13

Permit Holder: Canadian Natural Resources Limited

Authorized by BCER