

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3149
Inspection Date: 2026-08-26
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1020HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: C-a14-I Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

C-b14-I Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

C-c14-I Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

C-d14-I Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- Minor Flow detected from glove test. Building entry test- No alarms on personal monitor.

C-e14-I Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

C-f14-I Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

C-g14-I Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

C-h14-I Well appears active. ESD appears closed. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

Tanks on site-No concerns at time of inspection.

Test separator building entry test- No alarms on personal monitor. No concerns at the time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100109573
Well ID: 39774
Well Name: TOURMALINE ET AL HZ BIRCH C-A014-I/094-A-13
Location: NTS: C-A014-I/094-A-13

Permit: 100109573
Well ID: 39775
Well Name: TOURMALINE ET AL HZ BIRCH C-B014-I/094-A-13
Location: NTS: C-B014-I/094-A-13

Permit: 100109573
Well ID: 39776
Well Name: TOURMALINE ET AL HZ BIRCH C-C014-I/094-A-13
Location: NTS: C-C014-I/094-A-13

Permit: 100109573
Well ID: 39777
Well Name: TOURMALINE ET AL HZ BIRCH C-D014-I/094-A-13
Location: NTS: C-D014-I/094-A-13

Permit: 100109573
Well ID: 39778
Well Name: TOURMALINE ET AL HZ BIRCH C-E014-I/094-A-13
Location: NTS: C-E014-I/094-A-13

Permit: 100109573
Well ID: 39779
Well Name: TOURMALINE ET AL HZ BIRCH C-F014-I/094-A-13
Location: NTS: C-F014-I/094-A-13

Permit: 100109573
Well ID: 39780
Well Name: TOURMALINE ET AL HZ BIRCH C-G014-I/094-A-13
Location: NTS: C-G014-I/094-A-13

Permit: 100109573
Well ID: 39781
Well Name: TOURMALINE ET AL HZ BIRCH C-H014-I/094-A-13
Location: NTS: C-H014-I/094-A-13

Permit: 100115525
Facility ID: 00027570
Facility Name: TOURMALINE NIG CREEK C-014-I/094-A-13 002
Facility Type: Well Facility
Location: NTS: C- 014-I/094-A-13

Authorized by BCER