

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3150

Inspection Date: 2026-08-26

Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1107HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: D-22-J Pumpjack & Well appears inactive (due to turnaround). ESD appears closed. No barricades in place (Limited risk due to isolated location). Signage in place. Insulated tape wrapped around wellhead and flowline. Surface casing vent flow test- No Flow detected from glove test. Tanks on site-No concerns at time of inspection.

D-a22-J Pumpjack & Well appears inactive (due to turnaround). ESD appears closed. No barricades in place (Limited risk due to isolated location). Signage in place. Insulated tape wrapped around wellhead and flowline. Surface casing vent flow test- No Flow detected from glove test. Tanks on site-Loud hissing coming from propane tanks & odor on site (See attached). Officer informed area supervisor and an operator was dispatched to investigate.

A-32-J Pumpjack & Well appears inactive (due to turnaround). ESD appears open. No barricades in place (Limited risk due to isolated location). Signage in place. Missing plug on needle valve (See attached). Insulated tape wrapped around wellhead and flowline. Surface casing vent flow test- No Flow detected from glove test. Tanks on site-Filter coming from inhibitor fluid tank appears to be leaking from threaded connection and accumulating onto ground (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100014420
Well ID: 08175
Well Name: CNRL HZ BIRCH D- 022-J/094-A-13
Location: NTS: D- 022-J/094-A-13

Permit: 100071506
Well ID: 26422
Well Name: CNRL HZ BIRCH A- 032-J/094-A-13
Location: NTS: A- 032-J/094-A-13

Permit: 100073479
Well ID: 27190
Well Name: CNRL HZ BIRCH D-A022-J/094-A-13
Location: NTS: D-A022-J/094-A-13

Permit: 100014420
Facility ID: 00019098
Facility Name: CNRL BIRCH D-022-J/094-A-13 001
Facility Type: Well Facility
Location: NTS: D- 022-J/094-A-13

Permit: 100071506
Facility ID: 00024680
Facility Name: CNRL BIRCH A-032-J/094-A-13 001
Facility Type: Well Facility
Location: NTS: A- 032-J/094-A-13

Authorized by BCER