

## Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3151

Inspection Date: 2026-08-26

Inspection Outcome: Inspected

### Inspection Comment:

Proximity to Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1205HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: =Wellhead Suspended. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Polish rod removed. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Tanks on site-Out of service.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006574

Well ID: 04616

Well Name: CNRL BIRCH B- 050-I/094-A-13

Location: NTS: B- 050-I/094-A-13

Permit: 100010611

Facility ID: 00000067

Facility Name: CNRL BIRCH B-050-I/094-A-13 001

Facility Type: Battery Site

Location: NTS: B- 050-I/094-A-13

---

Authorized by BCER



Inspection Number: 2026-3151  
Inspection Date: 2026-08-26

Letter ID: L2604462  
Letter Date: 2026-08-28