

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3157
Inspection Date: 2026-08-26
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1309HRS.

Access road- Limited Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead appears active. No barricades in place (Limited risk due to isolated location). Signage in place. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor.

Tanks on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100029348
Well ID: 13904
Well Name: TOURMALINE HZ NIG B- 079-A/094-H-04
Location: NTS: B- 079-A/094-H-04

Authorized by BCER