

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3158
Inspection Date: 2026-08-31
Inspection Outcome: Inspected

Inspection Comment:

Proximity to Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1435HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Note: Occasional odors on lease- No alarms on personal monitor.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100002234
Well ID: 01681
Well Name: TOURMALINE NIG D- 075-B/094-H-04
Location: NTS: D- 075-B/094-H-04

Authorized by BCER