

Inspection Report

Permit Holder: Tourmaline Oil Corp.

Inspection: 2026-3162

Inspection Date: 2026-08-26

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1521HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead appears active. No barricades in place (Limited risk due to isolated location). Signage in place. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor.

Note: Occasional odors in proximity to wellhead- No alarms on personal monitor.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100032081

Well ID: 14691

Well Name: TOURMALINE NIG D- 092-B/094-H-04

Location: NTS: D- 092-B/094-H-04

Authorized by BCER