

Inspection Report

Permit Holder: Tourmaline Oil Corp.

Inspection: 2026-3163

Inspection Date: 2026-08-26

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1532HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- Flow detected from glove test (glove filled in 1 minute). Performed bubble test from 1539 to 1549- No bubble observed.

Building entry test- No alarms on personal monitor.

Pig Station- No concerns at time of inspection.

Tanks on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000576

Well ID: 00447

Well Name: TOURMALINE NIG B- 002-G/094-H-04

Location: NTS: B- 002-G/094-H-04

Permit: 100000576

Facility ID: 00018421

Facility Name: TOURMALINE NIGCREEK B-002-G/094-H-04 001

Facility Type: Well Facility

Location: NTS: B- 002-G/094-H-04



Inspection Number: 2026-3163
Inspection Date: 2026-08-26

Letter ID: L2604490
Letter Date: 2026-08-31

Authorized by BCER