

## Inspection Report

Permit Holder: VERMILION ENERGY INC.

Inspection: 2026-3173

Inspection Date: 2026-08-26

Inspection Outcome: Inspected

### Inspection Comment:

Site 01-24-081-14 was inspected at or about 1150 hours, it was 22 & hazy. The following was included in the inspection:

Access and signage: Signage clear and legible

Site: Wellsite clean and no vegetation concerns

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, leak detected at grease point on wellhead. Operator contacted, confirmed cleaned and tighten, maintenance planner will send valve tech to service on Aug 27

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Chemical tanks: leaks, grounds, caps, - no concerns

Riser & pig stations: chains, grounds, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100100503

Well ID: 32254

Well Name: VERMILION HZ MICA 01-24-081-14

Location: DLS: 01-24-081-14

Permit: 100101445

Facility ID: 00026286

Facility Name: VERMILION MICA 01-24-081-14 001

Facility Type: Well Facility

Location: DLS: 01-24-081-14

Permit Holder: VERMILION ENERGY INC.

---

Authorized by BCER