

Inspection Report

Permit Holder: Cardinal Energy Ltd.

Inspection: 2026-3179

Inspection Date: 2026-08-26

Inspection Outcome: Inspected

Inspection Comment:

Site 15-06-081-13 was inspected at or about 1220 hours, it was 27 & hazy. The following was included in the inspection:

Access and signage: Signage clear and legible

Site: Wellsite clean, some ruts and scouring at entrance, no vegetation concerns

Wellheads: Bull plugs, SCV, locks, leaks, - SCV no flow detected. Critical valves locked, no concerns

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100043651

Well ID: 18170

Well Name: CARDINAL MICA 15-06-081-13

Location: DLS: 15-06-081-13

Permit Holder: Cardinal Energy Ltd.

Authorized by BCER