

Inspection Report

Permit Holder: VERMILION ENERGY INC.

Inspection: 2026-3184

Inspection Date: 2026-08-28

Inspection Outcome: Inspected

Inspection Comment:

Site 01-33-081-14 was inspected at or about 1445. Vermilion representative on site. It was 16 and cloudy, 20 km wind with gust to 35 km (309NW).

Sludge in SE corner.

Peroxide treatment is in progress, rep turning 4th of 18 on. Tubs located on west (8) and south side (8). Due to rain rig mats were required, delaying commencement.

Odor at SE corner of site - light industrial.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100115429

Facility ID: 00027561

Facility Name: VERMILION MICA 01-33-081-14 001

Facility Type: Water Hub

Location: DLS: 01-33-081-14

Permit Holder: VERMILION ENERGY INC.

Authorized by BCER