

Inspection Report

Permit Holder: VERMILION ENERGY INC.

Inspection: 2026-3185

Inspection Date: 2026-08-31

Inspection Outcome: Inspected

Inspection Comment:

SITE INSPECTION OVERVIEW

Site 01-33-081-14 was inspected at approximately 1400 hours. A Vermilion representative was present on site during the inspection.

WEATHER AND SITE CONDITIONS

- * Weather was cloudy with a temperature of 19°C.
- * Winds were from 220° southwest at 15 km/h, with gusts up to 31 km/h.
- * No odour was present at the time of inspection.

TREATMENT STATUS AND NEXT STEPS

Treatment has been completed. The pond is currently full, with sludge observed in the northeast corner. Plans are in place to skim the pond on September 1 using a boom.

ATTACHMENT

A pond photograph is attached.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100115429

Facility ID: 00027561

Facility Name: VERMILION MICA 01-33-081-14 001

Facility Type: Water Hub

Location: DLS: 01-33-081-14

Permit Holder: VERMILION ENERGY INC.



Inspection Number: 2026-3185
Inspection Date: 2026-08-31

Letter ID: L2604512
Letter Date: 2026-09-01

Authorized by BCER