

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3190
Inspection Date: 2026-09-01
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Access road good, signage is present. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100108041
Well ID: 38936
Well Name: OVV HZ BRIARRIDGE 14-01-078-14
Location: DLS: 14-01-078-14

Permit: 100108041
Well ID: 38937
Well Name: OVV HZ BRIARRIDGE A14-01-078-14
Location: DLS: A14-01-078-14

Permit: 100108041
Well ID: 38938
Well Name: OVV HZ BRIARRIDGE B14-01-078-14
Location: DLS: B14-01-078-14

Permit: 100108041
Well ID: 38939
Well Name: OVV HZ BRIARRIDGE C14-01-078-14
Location: DLS: C14-01-078-14

Permit: 100108041
Well ID: 38940
Well Name: OVV HZ BRIARRIDGE D14-01-078-14
Location: DLS: D14-01-078-14

Permit: 100108041
Well ID: 38941
Well Name: OVV HZ BRIARRIDGE E14-01-078-14
Location: DLS: E14-01-078-14

Permit: 100108041
Well ID: 38942
Well Name: OVV HZ BRIARRIDGE F14-01-078-14
Location: DLS: F14-01-078-14

Permit: 100109285
Facility ID: 00027070
Facility Name: OVV BRIAR RIDGE 14-01-078-14 001
Facility Type: Well Facility
Location: DLS: 14-01-078-14

Authorized by BCER