

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3192
Inspection Date: 2026-09-01
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100073519
Well ID: 27273
Well Name: OVV CRP HZ SWAN B- 007-H/093-P-09
Location: NTS: B- 007-H/093-P-09

Permit: 100073580
Well ID: 27286
Well Name: OVV CRP HZ SWAN B-A007-H/093-P-09
Location: NTS: B-A007-H/093-P-09

Permit: 100073519
Facility ID: 00025103
Facility Name: OVV HERITAGE B-007-H/093-P-09 001
Facility Type: Well Facility
Location: NTS: B- 007-H/093-P-09

Permit: 100073580
Facility ID: 00025111
Facility Name: OVV HERITAGE B-007-H/093-P-09 002
Facility Type: Well Facility
Location: NTS: B- 007-H/093-P-09

Authorized by BCER