

Inspection Report

Permit Holder: Ovintiv Canada ULC

Inspection: 2026-3193

Inspection Date: 2026-09-01

Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

Packing on annulus valve of d-A5 weeping.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100054662

Well ID: 21368

Well Name: OVV ECOG SWAN D- 005-H/093-P-09

Location: NTS: D- 005-H/093-P-09

Permit: 100062284

Well ID: 23616

Well Name: OVV ECOG HZ SWAN D-B005-H/093-P-09

Location: NTS: D-B005-H/093-P-09

Permit: 100062285

Well ID: 23617

Well Name: OVV ECOG HZ SWAN D-A005-H/093-P-09

Location: NTS: D-A005-H/093-P-09

Permit: 100054662

Facility ID: 00022191

Facility Name: OVV SWANLAKE D-005-H/093-P-09 001

Facility Type: Well Facility

Location: NTS: D- 005-H/093-P-09

Permit: 100062284

Facility ID: 00023230

Facility Name: OVV HERITAGE D-005-H/093-P-09 003

Facility Type: Well Facility

Location: NTS: D- 005-H/093-P-09

Permit: 100062285
Facility ID: 00023231
Facility Name: OVV HERITAGE D-005-H/093-P-09 004
Facility Type: Well Facility
Location: NTS: D- 005-H/093-P-09

Authorized by BCER