

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3194
Inspection Date: 2026-09-01
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations.

Note: Packing weeping at C-A15-H

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100057296
Well ID: 22327
Well Name: OVV ECOG HZ SWAN C- 015-H/093-P-09
Location: NTS: C- 015-H/093-P-09

Permit: 100057297
Well ID: 22328
Well Name: OVV ECOG HZ SWAN C-A015-H/093-P-09
Location: NTS: C-A015-H/093-P-09

Permit: 100057298
Well ID: 22330
Well Name: OVV ECOG HZ SWAN C-B015-H/093-P-09
Location: NTS: C-B015-H/093-P-09

Permit: 100057296
Facility ID: 00022613
Facility Name: OVV HERITAGE C-015-H/093-P-09 001
Facility Type: Well Facility
Location: NTS: C- 015-H/093-P-09

Permit: 100057297
Facility ID: 00022614
Facility Name: OVV HERITAGE C-015-H/093-P-09 002
Facility Type: Well Facility
Location: NTS: C- 015-H/093-P-09

Permit: 100057298
Facility ID: 00022616
Facility Name: OVV HERITAGE C-015-H/093-P-09 003
Facility Type: Well Facility
Location: NTS: C- 015-H/093-P-09

Authorized by BCER