

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3195
Inspection Date: 2026-09-01
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and tank and sec contain and pigging station(s) meet current regulations.

Note: D-A17-H/93-P9 packing weeping

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100040508
Well ID: 17386
Well Name: OVV BISSETTE D- 017-H/093-P-09
Location: NTS: D- 017-H/093-P-09

Permit: 100055101
Well ID: 21463
Well Name: OVV ECOG HZ SWAN D-A017-H/093-P-09
Location: NTS: D-A017-H/093-P-09

Permit: 100055102
Well ID: 21464
Well Name: OVV ECOG HZ SWAN D-B017-H/093-P-09
Location: NTS: D-B017-H/093-P-09

Permit: 100069521
Well ID: 25740
Well Name: OVV ECOG HZ SWAN D-C017-H/093-P-09
Location: NTS: D-C017-H/093-P-09

Permit: 100040508
Facility ID: 00020576
Facility Name: OVV HERITAGE D-017-H/093-P-09 001
Facility Type: Well Facility
Location: NTS: D- 017-H/093-P-09

Permit: 100055101
Facility ID: 00022237
Facility Name: OVV HERITAGE D-017-H/093-P-09 003
Facility Type: Well Facility
Location: NTS: D- 017-H/093-P-09

Permit: 100055102
Facility ID: 00022238
Facility Name: OVV HERITAGE D-017-H/093-P-09 004
Facility Type: Well Facility
Location: NTS: D- 017-H/093-P-09

Permit: 100069521
Facility ID: 00024307
Facility Name: OVV HERITAGE D-017-H/093-P-09 007
Facility Type: Well Facility
Location: NTS: D- 017-H/093-P-09

Authorized by BCER