

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3196
Inspection Date: 2026-09-01
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048133
Well ID: 19419
Well Name: OVV SWAN D- 025-H/093-P-09
Location: NTS: D- 025-H/093-P-09

Permit: 100055970
Well ID: 21741
Well Name: OVV ECOG HZ SWAN D-A025-H/093-P-09
Location: NTS: D-A025-H/093-P-09

Permit: 100056118
Well ID: 21742
Well Name: OVV HZ SWAN D-B025-H/093-P-09
Location: NTS: D-B025-H/093-P-09

Permit: 100048133
Facility ID: 00021182
Facility Name: OVV HERITAGE D-025-H/093-P-09 001
Facility Type: Well Facility
Location: NTS: D- 025-H/093-P-09

Permit: 100055970
Facility ID: 00022370
Facility Name: OVV HERITAGE D-025-H/093-P-09 003
Facility Type: Well Facility
Location: NTS: D- 025-H/093-P-09



Inspection Number: 2026-3196
Inspection Date: 2026-09-01

Letter ID: L2604526
Letter Date: 2026-09-02

Authorized by BCER