

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3198
Inspection Date: 2026-09-01
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100047505
Well ID: 19317
Well Name: OVV ECOG SWAN C- 028-H/093-P-09
Location: NTS: C- 028-H/093-P-09

Permit: 100050573
Well ID: 20500
Well Name: OVV ECOG HZ SWAN C-A028-H/093-P-09
Location: NTS: C-A028-H/093-P-09

Permit: 100047505
Facility ID: 00021138
Facility Name: OVV HERITAGE C-028-H/093-P-09 001
Facility Type: Well Facility
Location: NTS: C- 028-H/093-P-09

Permit: 100050573
Facility ID: 00021787
Facility Name: OVV HERITAGE C-028-H/093-P-09 002
Facility Type: Well Facility
Location: NTS: C- 028-H/093-P-09



Inspection Number: 2026-3198
Inspection Date: 2026-09-01

Letter ID: L2604528
Letter Date: 2026-09-02

Authorized by BCER