

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3199
Inspection Date: 2026-09-01
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055038
Well ID: 21413
Well Name: OVV ECOG HZ SWAN A-A038-H/093-P-09
Location: NTS: A-A038-H/093-P-09

Permit: 100055039
Well ID: 21417
Well Name: OVV ECOG HZ SWAN A-B038-H/093-P-09
Location: NTS: A-B038-H/093-P-09

Authorized by BCER