

Inspection Report

Permit Holder: Tourmaline Oil Corp.

Inspection: 2026-3209

Inspection Date: 2026-09-02

Inspection Outcome: Inspected

Inspection Comment:

Inspection Summary

Site 06-06-081-15 was inspected at approximately 1320 hours. Weather conditions were sunny, with a temperature of 22°C & cloudy.

Inspection Findings

- Access and signage: Signage was clear and legible.
- Site condition: The wellsite was clean, with no vegetation concerns noted.
- Wellheads: Bull plugs, SCV, locks, and leaks were checked. No SCV flow was detected. Critical valves were locked, with no concerns noted.
- Meter/separator buildings: Locks, leaks, caps, and vents were checked, with no concerns noted.
- Chemical tanks: Leaks, grounds, and caps were checked, with no concerns noted.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100062500

Well ID: 23669

Well Name: TOURMALINE ALTIA PARKLAND 06-06-081-15

Location: DLS: 06-06-081-15

Permit: 100062500

Facility ID: 00023253

Facility Name: TOURMALINE PARKLAND 06-06-081-15 001

Facility Type: Well Facility

Location: DLS: 06-06-081-15

Permit Holder: Tourmaline Oil Corp.

Authorized by BCER