

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3212

Inspection Date: 2026-09-01

Inspection Outcome: Inspected

Inspection Comment:

Access and access signage inspected.

Pad clean.

Inspect well. No SCV flow observed. Wellhead protected.

Chem tanks inspected.

Miscellaneous insulation debris laying near chem tanks. See attached photos.

Lined pond on location, has some damage to one side of the fencing, ungulates may be able to jump the fence here into the pond area. South side of the pond. See photos.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100058258

Well ID: 22449

Well Name: CNRL HZ SUNDOWN B- 068-H/093-P-07

Location: NTS: B- 068-H/093-P-07

Permit: 100058258

Facility ID: 00022675

Facility Name: CNRL DEEPBASIN B-068-H/093-P-07 001

Facility Type: Well Facility

Location: NTS: B- 068-H/093-P-07

Permit: 100064467

AACT Number: 00001392

Site Type: Water Loading Station



Inspection Number: 2026-3212
Inspection Date: 2026-09-01

Letter ID: L2604554
Letter Date: 2026-09-03

Authorized by BCER