

Inspection Report

Permit Holder: Coelacanth Energy Inc.

Inspection: 2026-3231

Inspection Date: 2026-09-01

Inspection Outcome: Inspected

Inspection Comment:

- * Travel to COELACANTH HZ TWO RIVERS 09-32-082-15. sign in site orientation.
- * Meet and greet site supervisors.
- * Discuss operations and review documents.
- * Conduct and discuss site inspection with supervisors.
- * No concerns with this inspection at this time.
- * Sign out return to Dawson Creek

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100118844

Well ID: 51539

Well Name: COELACANTH HZ TWO RIVERS A09-32-082-15

Location: DLS: A09-32-082-15

Authorized by BCER