

## Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.

Inspection: 2026-3233

Inspection Date: 2026-09-02

Inspection Outcome: Inspected

### Inspection Comment:

- \* Travel to COP HZ INGA 04-09-088-23. Sign in, site orientation.
- \* Meet with site supervisors. discuss operations and review documents.
- \* Conduct and discuss site inspection with supervisors.
- \* No concerns at the time of completing this inspection.
- \* Sign out return to Dawson Creek.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100120530

Well ID: 54527

Well Name: COP HZ INGA M04-09-088-23

Location: DLS: M04-09-088-23

---

Authorized by BCER