

## Inspection Report

Permit Holder: Tourmaline Oil Corp.  
Inspection: 2026-3237  
Inspection Date: 2026-09-01  
Inspection Outcome: Inspected

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1200HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active (well last produced April 2026). ESD appears closed. No barricades in place (Limited risk due to isolated location). Signage in place. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Meter calibration tags appear up to date. No concerns at time of inspection.

Tanks and secondary containment on site-No concerns at time of inspection.

Pig Station- No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100002313  
Well ID: 01740  
Well Name: TOURMALINE NIG A- 006-G/094-H-04  
Location: NTS: A- 006-G/094-H-04

---

Authorized by BCER