

Inspection Report

Permit Holder: Strathcona Resources Ltd.

Inspection: 2026-3242

Inspection Date: 2026-09-02

Inspection Outcome: Inspected

Inspection Comment:

Access and access signage inspected.

Pad clean.

Inspect wells. No SCV flow observed. Wellheads protected. Signage clear and legible.

Chem tanks inspected.

Pig barrel inspected.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100060707

Well ID: 22988

Well Name: STRATHCONA ET AL BRASSEY C- 054-D/093-P-10

Location: NTS: C- 054-D/093-P-10

Permit: 100060708

Well ID: 22989

Well Name: STRATHCONA ET AL BRASSEY C-A054-D/093-P-10

Location: NTS: C-A054-D/093-P-10

Permit: 100060709

Well ID: 22990

Well Name: STRATHCONA ET AL BRASSEY C-B054-D/093-P-10

Location: NTS: C-B054-D/093-P-10

Permit: 100060710

Well ID: 22991

Well Name: STRATHCONA ET AL BRASSEY C-C054-D/093-P-10

Location: NTS: C-C054-D/093-P-10

Permit: 100060711
Well ID: 22992
Well Name: STRATHCONA ET AL HZ BRASSEY C-D054-D/093-P-10
Location: NTS: C-D054-D/093-P-10

Permit: 100060707
Facility ID: 00022901
Facility Name: STRATHCONA DEEPBASIN C-054-D/093-P-10 001
Facility Type: Well Facility
Location: NTS: C- 054-D/093-P-10

Authorized by BCER