

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3245
Inspection Date: 2026-09-02
Inspection Outcome: Inspected

Inspection Comment:

Access and access signage inspected.

Pad clean.

400bbl tanks x 2 and containment.

Inspect well. Audible hiss and missing plug on needle valve off of wellhead. See pictures. SCV is attached to a catchment. Wellhead protected. Signage clear and legible.

Text area lead who sent operator out same day to correct.

Separator and line heater buildings inspected.

Chem tanks inspected.

Pig barrel inspected.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100076032
Well ID: 28275
Well Name: OVV CRP HZ BRASSEY D- 041-D/093-P-10
Location: NTS: D- 041-D/093-P-10

Permit: 100076032
Facility ID: 00025580
Facility Name: OVV HERITAGE D-041-D/093-P-10 001
Facility Type: Well Facility
Location: NTS: D- 041-D/093-P-10

Permit: 100076032
Road Number: 02281
Segment IDs (Location): 001 (From NTS: A- 060-C/093-P-10 To NTS: A- 051-D/093-P-10)



Inspection Number: 2026-3245
Inspection Date: 2026-09-02

Letter ID: L2604603
Letter Date: 2026-09-08

Authorized by BCER