

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3249

Inspection Date: 2026-09-02

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-this is a follow up inspection to the one done in June 2026. In that inspection I questioned the earthen berm around the two 400bbl tanks onsite. The earth berm does not have a liner in it and the berm itself looks questionable as to the ability to contain. Can you have someone with CNRL contact me to discuss. Thank you, Ken Pittam

-No SCVF

-there is no Flammable symbol on the location signage.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001060

Well ID: 00810

Well Name: CNRL ET AL WILDMINT D- 045-A/094-H-02

Location: NTS: D- 045-A/094-H-02

Permit: 100001060

Facility ID: 00018463

Facility Name: CNRL WILDMINT D-045-A/094-H-02 001

Facility Type: Well Facility

Location: NTS: D- 045-A/094-H-02

Authorized by BCER