

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3250
Inspection Date: 2026-09-01
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1314HRS.

Access road- Limited Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- Flow detected from glove test (filled and blew off in 30 seconds).

Performed bubble test from 1315 to 1325- Bubble immediate & constant (See attached). Internal records indicate pressure test completed May 2025.

Results show flow rate of approx .26 M3/day.

Building entry test- No alarms on personal monitor. Building out of service.

Tanks on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048468
Well ID: 19515
Well Name: TOURMALINE NIG D- 007-F/094-H-04
Location: NTS: D- 007-F/094-H-04

Permit: 100048468
Facility ID: 00021233
Facility Name: TOURMALINE NIGCREEK D-007-F/094-H-04 001
Facility Type: Well Facility
Location: NTS: D- 007-F/094-H-04



Inspection Number: 2026-3250
Inspection Date: 2026-09-01

Letter ID: L2604608
Letter Date: 2026-09-08

Authorized by BCER