

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3256

Inspection Date: 2026-09-02

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- This well last produced in October 2025.
- the wellhead valves are not chained and locked. The flowline is not disconnected from the wellhead. No flow on meter.
- one pig barrel is missing the chain
- no blackened area around the flarestack.
- lease, access and location signage is compliant.
- no SCVF

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100023931

Well ID: 11917

Well Name: CNRL RING D- 088-F/094-H-09

Location: NTS: D- 088-F/094-H-09

Permit: 100024330

Pipeline Project ID: 000008064

Segment IDs (Location): 1 (From NTS: D- 088-F/094-H-09 To NTS: D- 099-F/094-H-09)

Authorized by BCER