

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-3260
Inspection Date: 2026-09-02
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

A# 16548 - Sept. 2, 2026: 11:50 on site.

Wellhead: SCVA ball valve handle was found in the open position. Flowline is connected / suspended and well valve handles are present/attached (3x) to wellhead.

Kermit last reported gas production rate: 2025-09 "Inactive Status".

Signage is compliant to standards.

Well Facility: Cata-Dyne regulator vent lines are present: Suspended Status.
Meter calibration service record: 2022

Storage: double wall tank on metal frame (1x) and double wall metal tanker (1x), both containments have SDS labels present, and grounded.

Flowline: flowline is connected to the wellhead, well building, and pipeline (Inactive Status).

Scentless Chamomile is present on site (scattered /low incidence).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038638
Well ID: 16548
Well Name: SABA O&G LAPRISE A- 010-L/094-H-05
Location: NTS: A- 010-L/094-H-05

Permit: 100039994
Pipeline Project ID: 000012533
Segment IDs (Location): 1 (From NTS: A- 010-L/094-H-05 To NTS: D- 091-H/094-G-08)



Inspection Number: 2026-3260
Inspection Date: 2026-09-02

Letter ID: L2604622
Letter Date: 2026-09-09

Authorized by BCER