

Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-3261
Inspection Date: 2026-09-02
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

A# 23358 - Sept. 2, 2026: 12:04 on site.

Wellhead: SCVA ball valve handle was found in the open position, no LEL gas was measured (Altair-5x), and no flow was observed. Wellhead flowline is connected, and valve handles are present (4x) which are not chained and locked.

Kermit last reported gas production rate: 2025-03 "Suspended Status".

Signage is compliant to standards.

Well Facility: Cata-Dyne regulator vent lines are present: Suspended Status.

Storage: double wall tanks (2x) on metal stand, SDS labels present, and grounded.

Flowline: flowline is connected to the wellhead, well building, and pipeline (Suspended Status).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100061782
Well ID: 23358
Well Name: SABA O&G ET AL LAPRISE D- 001-I/094-G-08
Location: NTS: D- 001-I/094-G-08

Permit: 100061782
Facility ID: 00023083
Facility Name: SABA O&G LAPRISECREEK D-001-I/094-G-08 001
Facility Type: Well Facility
Location: NTS: D- 001-I/094-G-08

Permit: 100062199

Pipeline Project ID: 000000145

Segment IDs (Location): 1 (From NTS: D- 001-I/094-G-08 To NTS: B- 100-E/094-H-05)

Authorized by BCER