

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3263
Inspection Date: 2026-09-02
Inspection Outcome: Inspected

Inspection Comment:

WA# 5222 - Sept. 2, 2026: 13:14 on site.

Wellhead: SCVA ball valve handle was found in the open position. Flowline is connected to wellhead and valve handles are present (4x).

Kermit last reported gas production rate: 2026-07 "Active Status".

Signage is compliant to standards.

Well Facility: none found on site.

Storage: double wall tank (1x) on a metal stand and single wall tank (1x) in a plastic secondary tub, SDS labels present, and grounded.

Flowline: flowline is connected to the wellhead and pipeline (Active Status).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100007454
Well ID: 05222
Well Name: CANLIN LAPRISE B- 088-F/094-H-05
Location: NTS: B- 088-F/094-H-05

Permit: 100008004
Pipeline Project ID: 000003215
Segment IDs (Location): 1 (From NTS: B- 088-F/094-H-05 To NTS: C- 072-E/094-H-05)

Authorized by BCER