

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3264

Inspection Date: 2026-09-02

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- walked in due to muddy access road
- active gas well inside of a large building
- no sour symbol on location signage but not required as not sour.
- lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100024594

Well ID: 12147

Well Name: CNRL RING D- 099-F/094-H-09

Location: NTS: D- 099-F/094-H-09

Permit: 100024330

Pipeline Project ID: 000008064

Segment IDs (Location): 2 (From NTS: D- 099-F/094-H-09 To NTS: D- 083-E/094-H-09)

Authorized by BCER