

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3266
Inspection Date: 2026-09-02
Inspection Outcome: Inspected

Inspection Comment:

WA# 4920 - Sept. 2, 2026: 14:07 on site.

Wellhead: SCVA ball valve handle was found in the open position, no LEL gas was measured, and no flow was observed. Flowline is connected to wellhead and valve handles are present (4x).

Kermit last reported gas production rate: 2026-07 "Active Status".

Signage is compliant to standards; signage is only posted at road entrance, a well ID/location identifier such as a placard is required at wellhead location.

Well Facility: none found on site.

Storage: none found/used on site.

Flowline: flowline is connected to the wellhead and pipeline (Active Status).

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100006984
Well ID: 04920
Well Name: CANLIN LAPRISE C- 012-L/094-H-05
Location: NTS: C- 012-L/094-H-05

Permit: 100013867
Pipeline Project ID: 000005582
Segment IDs (Location): 1 (From NTS: C- 012-L/094-H-05 To NTS: D- 093-E/094-H-05)

Authorized by BCER