

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3268

Inspection Date: 2026-09-02

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-active gas well. No chain and lock on wellhead valves and no flowline disconnect. 2 buildings and a 100bbl tank onsite.

-no flammable symbol on the wellhead building signage

-lease, access and location signage is compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100024592

Well ID: 12145

Well Name: CNRL RING A- 029-K/094-H-09

Location: NTS: A- 029-K/094-H-09

Permit: 100024699

Pipeline Project ID: 000008276

Segment IDs (Location): 2 (From NTS: A- 029-K/094-H-09 To NTS: D- 038-K/094-H-09)

Authorized by BCER