

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3269

Inspection Date: 2026-09-02

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-active gas well. No SCVF

-2 buildings onsite

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100024593

Well ID: 12146

Well Name: CNRL RING D- 038-K/094-H-09

Location: NTS: D- 038-K/094-H-09

Permit: 100024699

Pipeline Project ID: 000008276

Segment IDs (Location): 3 (From NTS: D- 038-K/094-H-09 To NTS: B- 057-K/094-H-09)

Authorized by BCER