

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3270

Inspection Date: 2026-09-02

Inspection Outcome: Inspected

Inspection Comment:

WA# 29585, 29847 (A), and 29848 (B) - Sept. 2, 2026: 16:02 on site.

Wellheads (3x): SCVA ball valve handle was found in the open position. Client is reporting/monitoring SCVF as per required standards.

Kermit last reported gas production rate: 2026-07 "Active Status".

Signage is compliant to standards.

Well Facility: Cata-Dyne: FISHER regulator vent lines are in place. Meter calibration date: 2025 and Orifice plate service record: 2024.

Storage: double wall tank (1x) on a metal stand and double wall tank (1x) on a metal skid, all tanks have SDS labels posted and are grounded.

Flowline: flowline is connected to the wellhead, facility, and pipeline (Active Status). Pig barrel safety chain is attached to PAV (7x).

Incidence of Scentless chamomile was noted on well pad and access road.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100078991

Well ID: 29585

Well Name: PETRONAS HZ BUBBLES D- 026-A/094-G-08

Location: NTS: D- 026-A/094-G-08

Permit: 100079272

Well ID: 29847

Well Name: PETRONAS HZ BUBBLES D-A026-A/094-G-08

Location: NTS: D-A026-A/094-G-08

Permit: 100079273

Well ID: 29848

Well Name: PETRONAS HZ BUBBLES D-B026-A/094-G-08

Location: NTS: D-B026-A/094-G-08

Permit: 100078991
Facility ID: 00018104
Facility Name: PETRONAS BUBBLES D-026-A/094-G-08 001
Facility Type: Well Facility
Location: NTS: D- 026-A/094-G-08

Permit: 100081890
Pipeline Project ID: 000023532
Segment IDs (Location): 1 (From NTS: D- 026-A/094-G-08 To NTS: D- 049-A/094-G-08)

Authorized by BCER