

Inspection Report

Permit Holder: Secure Waste Infrastructure Corp

Inspection: 2026-3272

Inspection Date: 2026-09-03

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

A6-26-84-14:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.
No surface casing vent flow. Location signage is on wellhead.

B6-26-84-14:

-wellhead into pipeline with cover over wellhead. No SCVF
-lease, access and location signage is compliant.
-the lease has a couple contamination observation posts onsite.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100012134

Well ID: 07474

Well Name: SECURE WASTE BOUNDARY A06-26-084-14

Location: DLS: A06-26-084-14

Permit: 100080380

Well ID: 30410

Well Name: SECURE WASTE BOUNDARY LAKE B06-26-084-14

Location: DLS: B06-26-084-14

Permit: 100012134

Facility ID: 00019018

Facility Name: SECURE WASTE BOUNDARYLAKE 06-26-084-14 002

Facility Type: Well Facility

Location: DLS: 06-26-084-14

Permit: 100080380
Facility ID: 00026091
Facility Name: SECURE WASTE BOUNDARYLAKE 06-26-084-14 005
Facility Type: Well Facility
Location: DLS: 06-26-084-14

Authorized by BCER