

Inspection Report

Permit Holder: Whitecap Resources Inc.

Inspection: 2026-3273

Inspection Date: 2026-09-03

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-H2O injection well with cover. Wellhead valves chained and locked. Flowline is disconnected from the wellhead. No SCVF

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001151

Well ID: 00882

Well Name: WHITECAP ET AL BOUNDARY 16-05-085-13

Location: DLS: 16-05-085-13

Authorized by BCER