

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3274
Inspection Date: 2026-09-02
Inspection Outcome: Inspected

Inspection Comment:

A# 5221 - Sept. 2, 2026: 12:52 on site.

Wellhead: SCVA ball valve handle was found in the open position, no LEL gas was measured (Altair-5x), and no flow was observed. Flowline is connected and valve handles are present (2x).

Kermit last reported gas production rate: 2026-07 "Active Status".

Signage is compliant to standards.

Well Facility: Cata-Dyne regulator vent lines are present. Flare stack flowline suspended status (blinded flowline).

Storage: single wall tank (1x) in metal secondary containment, drain plug in place, SDS labels present, and grounded.

Flowline: flowline is connected to the wellhead, well building, and pipeline (Active Status).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100007400
Well ID: 05221
Well Name: CANLIN LAPRISE C- 100-F/094-H-05
Location: NTS: C- 100-F/094-H-05

Permit: 100007400
Facility ID: 00018845
Facility Name: CANLIN LAPRISECREEK C-100-F/094-H-05 001
Facility Type: Well Facility
Location: NTS: C- 100-F/094-H-05



Inspection Number: 2026-3274
Inspection Date: 2026-09-02

Letter ID: L2604638
Letter Date: 2026-09-09

Authorized by BCER