

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3281
Inspection Date: 2026-09-09
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1140HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active (records indicated production as of April 2026). ESD appears closed. No barricades in place (Limited risk due to isolated location). Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor. No concerns at time of inspection.

Tanks on site-No concerns at time of inspection.

Pig Station- No concerns at time of inspection.

Note: Inspector performed brief site visit at C-36-B site construction to inspect C rings. Daily inspection records for Sept 9, 2026 were not completed at time of inspection. Records show additional dates were missed in August (See attached). Legislation states (j)when the structure contains fluid, it is inspected daily for leaks, and a record of inspection is maintained until the site is decommissioned. C-Ring was actively being filled with fluid. Freeboard was documented to be withing regulation.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000942
Well ID: 00729
Well Name: TOURMALINE NIG C- 036-B/094-H-04
Location: NTS: C- 036-B/094-H-04

Permit: 100120382
Facility ID: 00028322
Facility Name: TOURMALINE NIG CREEK C-036-B/094-H-04 001
Facility Type: Well Facility
Location: NTS: C- 036-B/094-H-04

Authorized by BCER