

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-3282
Inspection Date: 2026-09-03
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

WA# 29357, 29367 (A), and 29368 (B) - Sept. 3, 2026: 10:30 on site.

Wellheads (3x): SCVA ball valve handle was found in the open position. Client is reporting/monitoring SCVF as per required standards.

Kermit last reported gas production rate: 2026-07 "Active Status".

Signage is compliant to standards.

Well Facilities: Cata-Dyne: FISHER regulator vent lines are in place. Meter calibration date: 2024 and Orifice plate service record: 2026.

Storage: double wall tank (1x) on a metal stand, SDS labels posted, and grounded.

Flowline: flowline is connected to the wellheads, facilities, and pipeline (Active Status). Pig barrel safety chains are each attached to associated PAVs (7x).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100078419
Well ID: 29357
Well Name: PETRONAS HZ BUBBLES B- 067-I/094-G-01
Location: NTS: B- 067-I/094-G-01

Permit: 100078452
Well ID: 29367
Well Name: PETRONAS HZ BUBBLES B-A067-I/094-G-01
Location: NTS: B-A067-I/094-G-01

Permit: 100078453
Well ID: 29368
Well Name: PETRONAS HZ BUBBLES B-B067-I/094-G-01
Location: NTS: B-B067-I/094-G-01

Permit: 100078419
Facility ID: 00017882
Facility Name: PETRONAS BUBBLES B-067-I/094-G-01 001
Facility Type: Well Facility
Location: NTS: B- 067-I/094-G-01

Authorized by BCER