

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3287

Inspection Date: 2026-09-03

Inspection Outcome: Inspected

Inspection Comment:

WA# 26543 (D-22-F) and 17841 (C-22-F) Sept. 3, 2026: 13:15 on site.

Wellhead: SCVA ball valve handle was found in the open position; client is monitoring/reporting SCVF to standards.

WA# 26543: wellhead flowlines are connected to well, all well valve handles are being chained and locked. Flowline is blinded at pipeline.

WA# 17841: all wellhead flowlines are disconnected with all well valve handles being removed.

Signage is compliant to standards.

Well Facility: Suspended Status - Out of Service

Storage: all storage tanks on site have SDS labels are posted and tanks grounded (Out of Service).

Flowline: flowline is blinded at pipeline (Suspended Status).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100043016

Well ID: 17841

Well Name: PETRONAS BEG C- 021-F/094-G-01

Location: NTS: C- 021-F/094-G-01

Permit: 100071893

Well ID: 26543

Well Name: PETRONAS BEG D- 022-F/094-G-01

Location: NTS: D- 022-F/094-G-01

Permit: 100043016
Facility ID: 00020690
Facility Name: PETRONAS BEG C-021-F/094-G-01 001
Facility Type: Well Facility
Location: NTS: C- 021-F/094-G-01

Permit: 100071893
Facility ID: 00024745
Facility Name: PETRONAS BEG D-022-F/094-G-01 001
Facility Type: Well Facility
Location: NTS: D- 022-F/094-G-01

Authorized by BCER